

ERRORS | INEX. | CAUSE | STAGE | DRILL

SOLO TOTAL	SOLO TYPE	NIGHT TOTAL	NIGHT TYPE	INST.	LINK
338.	5.				
[illegible]	[illegible]	[illegible]	[illegible]	[illegible]	[illegible]

DURATION OF FLIGHT: H. 2 M. 45 | TIME 12.25 | 1225

DUTY & HISTORY: Flying Prac. — flying practice

Cause From due pilot attempting turn at too low a speed whilst
Insert:- Two pilots attempting turn at too low a speed, whilst
practicing single engine flying aircraft spun in
practising Single engines flying, a/c spun in
Aircraftsman Archie Crosland
Aircraftsman Archie Crosland

H:F:N | DAWN:DUSK | DROME: N | F2

WT. 6521/2940. 143 M/- 6218. PAT. NOS. 225089, 297892 C.C. 90626 H

MONTH: 10/6 | COMMAND | UNIT CLASS | AIRCRAFT TYPE | FLIGHT | DAMAGE | CAS.